



Common Precautions for XB4A/XB4B Connectors

■ Safety Precautions



Precautions for Correct Use

● For Operating


- (1) Regarding the connector stacking operation, it should be confirmed there is no extreme displacement and tilt in the stacking contact areas between a plug and a socket before the stacking operation of the connectors.
 - An incomplete stacking state may cause the failure of contact reliability.
- (2) Ensure that the connector stackings are fully seated.
 - An incomplete stacking state may cause the failure of contact reliability.
- (3) Do not apply an extreme load when inserting or drawing out the connector.
 - The connector may be damaged, resulting in faulty contacts.
- (4) When stacking the plug and socket, press the back side of printed circuit board mounted with them and then couple with as little twisting force as possible.
 - Doing so may cause the terminal and housing to change shape or the housing to crack.



- (5) When drawing out, hold the edge of the printed circuit board near the connector and remove as vertically as possible, as described in the figure below.
 - Drawing out the plug with too much force may have possibility to change shape of terminal solder/housing crack.



- (6) Do not insert a foreign object such as a tweezers into the connector stacking contact area.
 - Doing so may cause the plating peel off and deform the shape of the terminal.



● For Designing


- (1) When mounting the connector to the FPC, design the FPC so that extreme peel force should not be applied directly on to the connector.
 - If the FPC bends near the connector, or if the FPC is used with extreme peel force directly on to the connector, it may cause a contact loss.
- (2) If the connector-mounted FPC is installed at a location or in any equipment that will subject the FPC to continuous shake or movement, secure the FPC or take any countermeasure against FPC disconnection from the connector.
- (3) Do not use plural connectors on same PCB.
 - Doing so may cause solder and housing crack.
- (4) When locating the connector on the printed circuit board, be sure to allow space for the stacking operation.
- (5) Ensure a metal mask thickness of $t = 0.10$ to 0.15 mm.
 - The recommended open area of the metal mask is 90% of the printed circuit board's mating dimensions as shown in the dimensional diagrams.

● For Mounting

- (1) The reflow conditions are as stated in OMRON's specifications and guidelines.
 - These conditions, however, depend on the type of solder, the manufacturer, the amount of solder, the size of the circuit board, and the other mounting materials.
- (2) When mounting the connector by manual soldering, observe the following precautions to ensure contact reliability.
 - Conditions for manual soldering: $350 \pm 10^\circ\text{C}$ 3 ± 1 sec
 - Do not apply an excessive amount of solder. Excessive solder will cause the flux creap.
 - Do not apply the soldering iron to the mounting terminal. Doing so may cause the connectors to change shape.
 - Do not apply the soldering iron to any parts of the connector other than the mount attachments. Doing so may cause the connector to change shape.

Operating XB4A/XB4B


Board to Board Connectors parts




Handling Methods

● How to couple a connector

- (1) Position a plug with a socket.



- (2) Insert the connector until it becomes horizontal.



● How to draw out the connector

- (1) Hold the edge of the printed circuit board near the connector and draw out as vertically as possible.

